

Overview for „VNWA3 Help“ (pdf File)“

Item	Page
A	
Audio Issues	462
B	
Balun Characterization	399
Binary S-Parameter File Format	440
C	
Calibration (Instrument)	77
Master Calibration	88
Calibration for a Two Port S-Parameter measurement	84
Low loss capacitor calibration	90
Configuration (automaticly) of the Software for usage with a DG8SAQ VNWA (Auto Setup)	44
Configuration (manually) of the Software for usage with a DG8SAQ VNWA	54
Configuring and running the VNWA application under Windows Vista, 7, 8 or 10	58
Cursor	316
Custom:	357
Trace Data Manipulation	357
Example 1: Determining an impedance from a transmission measurement	357
Example 2: Unitarity relation	359
Example 3: Subexpressions	360
Example 4: Displaying the Phase of an Impedance	362
Example 5: Calculating various properties of an inductor or capacitor measured in transmission	364
Available Syntax	
Crystal Analyzer: extracting Resonator Model Parameters	388
General	388
Example 1: Reflection Measurement	388
Example 2: Transmission Measurement	390
General Hints	391
Analyzing a batch of crystals	392
Example 3: Mixed measurements with virtual ground calibration	392

Controlling the VNWA via TCP/IP	416
Controlling the VNWA by WINDOWS Messages	421
Controlling the VNWA by a Script File	425
Controls Outside Window, Missing Controls	460
D	
Dynamic Range Considerations	456
E	
Error Correction Models	402
Extracting Calibration Kit Parameters	379
F	
File Options	147
Functional Principle	5
Frequently asked Questions	464
G	
Generating Debug Output	490
H	
Hardware Overview	4
Hardware Troubleshooting	478
Help	295
Help	296
Configure Help	297
Home	298
About	
How to reduce CPU Load	489
I	
Impedance Measurement	338
The Standard Method	338
The I-Method	338
The V-Method	338
The RF-IV-Method	339
Summary	339

Immunity of Impedance Measurements to Interference	405
Importing and manipulating a Background Image	375
Installation of Driver and Software	15
Instrument Accuracy Considerations	323
Calibration Error (Port Mismatch) and Linearity	323
Warm-Up, Drift after Power-Up	326
Dynamic Range and Noise Performance	327
Spurious Responses	328
Narrow Band Interferers	328
Wideband Interferers	330
Interfacing Zplots	410
K	
Keyboard Shortcuts	321
L	
LCR - Meter	302
LPT Signal Conditioner	455
M	
Marker Summary	306
Adding a Marker	306
Moving a Marker	306
Removing Markers	307
The Marker Caption	308
Extended Marker Informations	309
Available Markers	312
Bandwidth Marker Issues	313
Switching Markers OFF for specific traces	314
Copying Marker Frequency Information	315
Changing Marker Symbol Size and Colour	315
Non-Transparent Markers	458
Matching Tool: performing a Matching Analysis	381
Determining the impedance environment for optimum DUT performance	381
Determining the matching networks	382
Matching Network Tutorial	384
Memory spaces	75

Measurement	95
Example: a simple One Port measurement	97
Example: simple Two Port	106
Interpretation of Two Port measurements	126
Measurements	164
Direction	165
Enforce Sweep	166
Calibrate	167
S-Parameters	168
Power Sweep	170
Port Extensions	176
Measuring RF-ID Tags	367
Measuring Antenna Radiation Patterns	407
Multiple VNWA Support	319
Very Low Frequency Measurements	410
O	
Options	250
Select Instrument (only visible, if N2PK support is activated)	251
Operation Modes	252
Bridge Modes	253
RF-IV Mode	254
Spectrum Analyzer and Tracking	
Generator Mode	256
Signal Generator Mode	259
Frequency Meter Mode	264
Frequency Meter Postprocessing DLL	270
Calibrating VNWA System Clock	
Using Frequency Meter	271
Screen Saver	293
Preset	294
Optimizing USB Traffic for Modulator Use	450
R	
Recovering corrupted Flash Memory	475
Renormalized Smith Chart	373
Remote-Controlling the VNWA	414

S

Setup (VNWA, default)	274
Interface Type	276
USB Settings	277
Audio Settings	279
Audio Level	281
Calibrate System Timing Tab	284
Timing Instrument Settings Tab	285
Misc. Settings	288
Setup (N2PK-VNA)	292
Settings	178
Frequency Range	179
Diagrams Sweep (VNWA)	181
Diagrams Zoom	182
Diagrams Display	183
Traces	184
Grid Options	186
Storage Screen	191
Transparent Screen	193
Marker Caption	195
Sweep (VNWA)	196
Sweep (Spectrum Analyzer)	199
Sweep (N2PK-VNA)	201
Power Levels	202
Average, Peak Hold, Autosave	204
Averaging / Peak Hold	205
Autosaving	207
Smoothing	208
Time Domain	210
Calibration Kit	211
S-Parameter Test Set	403
Controlling an S-Parameter Test Set via DLL Plug-In	404
Sweep Modes	331
Ultra fast Sweeps	333
Simultaneous Capture with two Sound Cards	335

T

Time Domain Measurement (Information)	146
Time Domain Measurements	340
Introduction to Tlme Domain Measurements	341
Time Domain Reflectometry	341
Time Domain vs. Frequency Domain	342
Finite Frequency Range Problem, Windowing	342
Band Pass vs. Low Pass Mode	343
Band Pass Processing	343
Low Pass Processing	344
Fourier Transform Options	345
Nyquist Criterion and Aliasing	345
Time Resolution	346
T-Check	491
Time Domain Reflectometry: Impulse Response	347
VNWA time domain reflectometry basics	347
Example	347
Time Domain Reflectometry Step Response	350
Time Domain Gating and Inverse FFT	352
Tuning Filters in the Time Domain	355
Tools	215
Matching Tool	216
Restore Unmatched	217
Copy Display Buffer Data to S2P Buffer	218
Crystal Analyzer	219
3 - Port Analyzer	220
Specification Tester	221
Source Code	226
Complex Calculator	228
Realtime Expression Evaluator	230
Optimizer	235
Custom Plotter	239
Virtual Keyboard	243
AsCII Import Tool	245
Data Client	247
Configure Tools	149
Three-Port Analyzer: Analyzing Balanced Components	396
Import or measure the 3-Port S-Parameters of your DUT	396
Start the 3-Port Analyzer	396
Observe the result in the main window	396
Perform a Matching Analysis	397
Perform a common mode analysis	397

U

USB Troubleshooting Guide	473
User Data Postprocessing	441

V

Verification of Proper Operation	465
Virtual VNWA Instruments	427
VNWA3E Presentation	11
VNWA3 Application Installation	32
VNWA Virtual Demo Device	428
VNWA Data Client	434
VNWA RC Client	438
VNWA Final Comissioning Test	487

Z

Zoom Functionality	304
---------------------------	------------